

Oil Field Environmental Incident Summary

Incident: 20151029091557

Date/Time of Notice: 10/29/2015 09:15

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: JOHN 1-20H

Field Name: PARSHALL

Well File #: 16583

Date Incident: 10/28/2015

Time Incident: 12:25

Facility ID Number:

County: MOUNTRAIL

Twp: 153

Rng: 89

Sec: 20

Qtr: SW SE

Location Description:

Submitted By: Keith Kallberg

Received By:

Contact Person: Keith Kallberg
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels			0	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 11/27/2015

Clean Up Concluded: 11/9/2015

Risk Evaluation:

Low

Areal Extent:

Offsite impact area was to the SSE next to a gravel pit area, 100 ft. x 220 ft. estimated

Potential Environmental Impacts:

Low

Action Taken or Planned:

The well was shut in and emergency services was contacted and monitored the fire, when the flames subsided they (Parshall FD) went in and dosed the area and checked for hot spots.

Wastes Disposal Location: TBD

Agencies Involved: Local Fire Department, Parshall

Updates

Date: 10/29/2015 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release impacted area off location. Followup required.

Date: 12/15/2015 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 13:35. 21 degrees F, cloudy, NW wind 5-10 mph. Observed site and took photos. It appeared that the vegetation had been burned along the side slope of the eastern part of the well pad and beyond the fenceline in an area used to mine gravel. Observations did not show any petroleum impacts to the soil in areas where the snow cover was moved. No further followup needed at this time.